

0655Z 18 MAR 64

SECRET

DIRECTOR

25X1A

OPS 1-12

TOR 0240Z 18 MAR 64

25X1A

25X1A

PRIORITY

INFO

CITY

0163

25X1A

- A. S064A
- B. B/119/7,280/ 25X1A
- C. HTA-3B/D-19/2°/78 DEGREES
- D. 1.75 2.14/2.08 2.04
- E. 9L/8402/223-15-4-3 OR/248-8-11-3
- F. (1) COLD AND MOIST
- (2) GOOD
- (3) FAIR - GOOD
- (4) GOOD
- (5) GOOD
- (6) GOOD
- (7) OPERATING

Q. REMARKS: TAKE RECEIVED 16/1930Z MAR IN UNCOVERED STEEL BOXES. TRACKER RECEIVED FOR S0444 IN GOOD CONDITION. DURING ORIGINAL BREAK-DOWN, TAKE WAS NOTED TO BE COLD AND MOIST. ALTHOUGH CORRECTIVE MEASURES WERE TAKEN FOR STATIC ELECTRICITY AFTER S024A, IT WAS NOTED

SECRET

25X1A

0163 (IN 68522)

S E C R E T

PAGE TWO

ON 9L FIRST 200 FRAMES. POSSIBLY DUE TO CONDITION OF FILM. SLIGHT  
CREASE IN FIRST 50 FRAMES 9R DUE TO SPLICE TO LEADER. SAME PRESSURE  
MARKS THAT WERE NOTED ON S014A AND S034A WERE NOTED AGAIN ON BOTH 9L  
AND 9R IN FIRST 100 FRAMES. NEGATIVE DENSITY SPOTS 1/16" IN DIA,  
ONE INCH APART IN THE MIDDLE OF FRAME WERE NOTED IMMEDIATELY AFTER  
MANUFACTURER SPLICE IN FRAME 1495R. A FEW MINOR PINHOLES AND A  
COUPLE OF MINOR ABRASIONS WERE NOTED IN PRODUCT. FRAMES 0307R AND  
0693R WERE TORN IN TACKY ROLLER CLEANER. MANUFACTURER SPLICES WERE  
NOTED ON FRAMES 0002L, 0203R, AND 1495R.

END OF MESSAGE

S E C R E T